

2005 Ford EXPLORER

Submodel: | Engine Type: V6 | Liters: 4.0
Fuel Delivery: FI | Fuel: GAS

DTC Code P1804

DTC Code:	P1804
Description: 4WD Hi Indicator Circuit Failure	
Probable Causes:	<div><div>1. Sensor or solenoid faulty</div><div>2. Connector terminal contact is damaged or corroded</div><div>3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage</div><div>4. Update control unit software - Check for the latest control unit update</div><div>5. Powertrain or Engine Control Module faulty</div></div>